VERTICAL TURBINE PUMPS



EFFICIENCY ADJUSTMENT FOR STAGING	
STAGES	NUMBER OF POINTS
1	Lower 1.4
2	Lower .8
3	Lower .4
4	Lower .2

NOTE: ANY CHANGE IN EFFICIENCY AFFECTS EITHER THE HEAD OR HORSEPOWER CORRESPONDINGLY

HYDRAULIC PERFORMANCE WARRANTY	CURVE NO.	IMPELLER NO.	IMPELLER DIA.	TAKEN FROM
Guaranteed at designated point only, and contingent on: Proper flow to pump suction; Proper submergence; Fluid free of gas, air & abrasives; Proper lateral setting of impeller	1	2626083	10.25 x 10.88	63016
	2	2626083	9.88 x 10.62	63053
	3	2626083	9.50 x 10.25	63256
	4	2626083	8.75 x 9.56	63353

Customer _____

Item _____

Peerless Ref. No:

Laboratory Performance — BOWL 2626067 CIE

SIZE 14MC — RPM 1160 — CURVE 4806420

PUMP DESCRIPTION: Driver _____; Head _____; Column _____

GUARANTEED BOWL☐ FIELD☐ PERFORMANCE: Capacity _____ gpm; Head _____ ft; Eff _____ %; BHP _____

Peerless Pump Company
A member of the Sterling Group