NO. 246

DE LAVAL TURBINE INC. TRENTON 2, NEW JERSEY

CC 84636

TEST RESULTS OF U. S. BUREAU OF RECLAMATION Units #6, #7, #8
UNIT NO 6 FRENCHMAN HILLS
DC 6092
CENTRIFUGAL PUMPING UNIT
PW 2028 @ 16-1/2" DIAM.

ORDER NO. 702614
TYPE U24/20D
SPEED 900 RPM
SUCTION
DATE 4-12

Frenchman Hills Units #6, #7, #8



This is a true and correct copy of the shop test to the best of my knowledge and belief.

R. Peck
R. PECK - LIAISON ENGINEER

This is a true and correct copy of the shop test to the best of my knowledge and belief.

L. C. Buller
L. C. Buller
Resident Inspector

APPROVED as to general design and controlling dimensions. Approval does not relieve the contractor of responsibility for correctness of details, nor does it waive any requirement of the specifications unless otherwise specifically stated in writing by the contracting officer or his representative.
MAY 1 2 1965
Date
J. J. Burnard
Chief, Hydraulic Machinery Branch

Withhold shipment (See letter)

B-80/FR Hills